

Inspection Photos

09/4/2025

Operator: EAGLE OPERATING INC - 26155

Location ID: 398233

Inspection Doc: 718100789

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 398233



Photo 1: Photos taken from the south end of the Location. Photos provide an overview of the Location from facing northwest and northeast. Location is predominantly bare, or vegetated by noxious weeds (Halogeton).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 398233



Photo 2: Photo example showing surface of the Location. Halogeton observed established throughout the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 398233



Photo 4: Photo of the adjacent reference area for comparison.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources