

Inspection Photos

09/4/2025

Operator: EAGLE OPERATING INC - 26155

Location ID: 397838

Inspection Doc: 718100791

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 397838



Photo 1: Photos taken from the north end of the Location. Photos provide an overview of the Location from facing south and southwest. The north/west ends of the Location is predominantly bare, or vegetated by noxious weeds (Halogeton).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 397838



Photo 2: Photo taken from the North end of the Location, facing southwest. Photo example showing areas of the Location where desirable plant establishment is not occurring. Areas are predominantly bare, or vegetated by noxious weeds (Halogeton).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 397838



Photo 3: Photo taken from the southwest end of the Location, facing northeast. Photo example showing areas of the Location where desirable plant establishment is not occurring. Areas are predominantly bare, or vegetated by noxious weeds (Halogeton).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources