

Inspection Photos

09/4/2025

Operator: DIAMOND BACK DRILLING &
SUPPLY INC - 24120

Location ID: 398240

Inspection Doc: 718100793

Rio Blanco County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398240



Photo 1: Cable/debris remaining on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: DIAMOND BACK DRILLING & SUPPLY INC - 24120

Location ID: 398240



Photo 2: Cable/debris remaining on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources