

## Inspection/Audit Photos

Location: UTAH GAS OPLTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 09/4/2025



Photo # 2903 Entrance to location



Photo # 2914 Location

## Inspection/Audit Photos

Location: UTAH GAS OPLTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 09/4/2025



Photo # 2905 Location



Photo # 2912 Location

## Inspection/Audit Photos

Location: UTAH GAS OPLTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 09/4/2025



Photo # 2920 NW corner of location



Photo # 2921 NE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OPLTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7336 PAD

Location ID: 316082

Date: 09/4/2025



Photo # 2923 SE corner of location



Photo # 2924 SW corner of location