

# Final Reclamation Inspection

August 11, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 330065

Inspection Document #: 718800729

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: PSC #32-10  
Location ID: 330065



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation, including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*), was observed across the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: PSC #32-10  
Location ID: 330065



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: PSC #32-10  
Location ID: 330065



**Photo 5.** Photo taken of the tank battery location, facing northeast. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) and cheatgrass (*Bromus tectorum*) dominates the location.



**Photo 6.** Photo taken of the tank battery location, facing north. See comments under Photo 5.

Inspection Photos  
Location Name: PSC #32-10  
Location ID: 330065



**Photo 7.** Photo taken of the tank battery location, facing south. See comments under Photo 5.



**Photo 8.** Photo taken of the tank battery location, facing west. See comments under Photo 5.

Inspection Photos  
Location Name: PSC #32-10  
Location ID: 330065



**Photo 9.** Photo taken of ground cover at the location. Photo illustrates cheatgrass (*Bromus tectorum*), a List C Noxious Weed Species, and kochia (*Bassia scoparia*).



**Photo 10.** Photo taken of the reference area to the location, southwest of the location, facing northwest. Photo illustrates disturbed rangeland with weedy annual vegetation, including kochia (*Bassia scoparia*).

