

Final Reclamation Inspection

August 18, 2025

Operator: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410482

Inspection Document #: 718800733

Yuma County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FITCH #1-9
Location ID: 410482



Photo 1. Photo taken from the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetative establishment cannot be determined as the site is located within fallow cropland at the time of this inspection.



Photo 2. Photo taken from the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: FITCH #1-9
Location ID: 410482



Photo 3. Photo taken from the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing west. See comments under Photo 1.