

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-66S102W/14SWNW

Location ID: 322313

Date: 9/8/2025



Location Overview/Weeds – Photo #00594



Location – Photo #00595

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-66S102W/14SWNW

Location ID: 322313

Date: 9/8/2025



Location/Wildlife Entry Hazard/Weeds – Photo #00597



Location – Photo #00601

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-66S102W/14SWNW

Location ID: 322313

Date: 9/8/2025



Location/Weeds – Photo #00598



Unused Equipment/Weeds – Photo #00599

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-66S102W/14SWNW

Location ID: 322313

Date: 9/8/2025



Debris – Photo #00603



Wildlife Entry Hazard – Photo #00600

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-66S102W/14SWNW

Location ID: 322313

Date: 9/8/2025



**Incorrect Operator Information on Wellhead Sign – Photo
#00596**