

# Inspection Photos

**08/20/2025**

**Operator:** BOOCO'S CONTRACT SERVICES INC -  
#9006

**Location ID:** 316789

**Inspection Document #:** 712300214

Routt County, CO

Logan Maxwell  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Peiltier 1-11H  
Location ID: 316789



**Photo 1.** Photos 1-4 taken as overview of the Location, near the center of the former well, facing north, east, south, and west.



**Photo 2.** See comments under Photo 1.

Inspection Photos  
Location Name: Peiltier 1-11H  
Location ID: 316789



**Photo 3.** See comments under Photo 1.



**Photo 4.** See comments under Photo 1.

Inspection Photos  
Location Name: Peiltier 1-11H  
Location ID: 316789



**Photo 5.** Photo taken of one of the four remaining guy line anchors still left on Location.



**Photo 6.** Photos 6-9 taken of the cut slope on the eastern portion of the Location. Photos illustrate that some areas remain bare with vegetation, which has led to destabilization and erosion on the cut slope.

Inspection Photos  
Location Name: Peiltier 1-11H  
Location ID: 316789



**Photo 7.** See comments under Photo 6. Red arrow indicates where rill erosion has started to occur.



**Photo 8.** See comments under Photo 6. Red arrows point to bare slopes and where erosion has started to occur.

Inspection Photos  
Location Name: Peiltier 1-11H  
Location ID: 316789



**Photo 9.** See comments under Photo 6.



**Photo 10.** Photos 10-13 taken of examples of noxious weeds seen across the Location (including Canada Thistle, Bull Thistle, and Houndstongue.)

Inspection Photos  
Location Name: Peiltier 1-11H  
Location ID: 316789



**Photo 11.** See comments under Photo 10. Example of large patch of Canada Thistle (Red circle).



**Photo 12.** See comments under Photo 10. Example of Houndstongue.

Inspection Photos  
Location Name: Peiltier 1-11H  
Location ID: 316789



**Photo 13.** See comments under Photo 10. Example of bull thistle.



**Photo 14.** Photos 12-14 taken on the Fill slope on the western portion of the Location, illustrating rill and gully erosion, undercutting vegetation.



Inspection Photos  
Location Name: Peiltier 1-11H  
Location ID: 316789



**Photo 15.** See comments under Photo 12. Red arrow points to rill erosion.



**Photo 16.** See comments under Photo 12. Red arrow points to gully erosion occurring undercutting the vegetation.

