

Inspection Photos
Location Name: Briggs #1
Location ID: 333222



Photo 1 Location.

Photo 2 Tank battery sign.

Inspection Photos
Location Name: Briggs 1
Location ID: 333222



Photo 3 Tank Battery.

Photo 4 Gas Meter Run.

Inspection Photos
Location Name: Briggs 1
Location ID: 333222



Photo 5 PR water vessel.

Photo 6 ECD & Horizontal Heated separator.

Inspection Photos
Location Name: Briggs 1
Location ID: 333222



Photo 7 Wellsite/Pumpjack.



Photo 8 Wellhead.

Inspection Photos
Location Name: Briggs 1
Location ID: 333222



Photo 9 Wellsite sign.

Photo 10 Ancillary equipment.