

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401



Photo # 6969 From entrance to location



Photo # 6970 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401



Photo # 6971 Location



Photo # 6972 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401



Photo # 6973 Location



Photo # 6974 Open ended load line

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401



Photo # 6975 Open ended piping near wellhead/wildlife hazard



Photo # 6976 Open ended piping near wellhead/wildlife hazard

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401




Photo # 6977 Unmarked deadman



Photo # 6978 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401



Photo # 6979 Same unmarked deadman



Photo # 6980 Debris

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401



Photo # 6981 Debris




Photo # 6982 Wellhead sign has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401



Photo # 6983 Battery sign has previous operators name

Photo # 6984 Tank label has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 247-25 Pad

Location #: 324401



Photo # 6985 Tank label has previous operators name