

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1001 PAD

Location ID: 314307

Date: 09/8/2025



Photo # 2977 Entrance to location




Photo # 2986 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1001 PAD

Location ID: 314307

Date: 09/8/2025



Photo # 2978 Location



Photo # 2983 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1001 PAD

Location ID: 314307

Date: 09/8/2025



Photo # 3013 SE corner of location



Photo # 3014 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1001 PAD

Location ID: 314307

Date: 09/8/2025



Photo # 3015 NW corner of location



Photo # 3016 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1001 PAD

Location ID: 314307

Date: 09/8/2025



Photo # 2993 Hole in meter house open to wildlife/available for entry by wildlife