

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1056 PAD

Location ID: 315520

Date: 09/8/2025



Photo # 3030 Entrance to location



Photo # 3038 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1056 PAD

Location ID: 315520

Date: 09/8/2025



Photo # 3031 Location



Photo # 3037 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1056 PAD

Location ID: 315520

Date: 09/8/2025



Photo # 3048 SE corner of location



Photo # 3049 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1056 PAD

Location ID: 315520

Date: 09/8/2025



Photo # 3050 NW corner of location



Photo # 3051 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1056 PAD

Location ID: 315520

Date: 09/8/2025



Photo # 3033 Wellhead sign lacks required information/not in compliance with CECMC rules

