

Inspection Photos

Location Name: STATE LEASE 81-66N64W/16NESW

Location #: 326993



Photo #1

State Lease 81 23-16 (123-13979) Wellsite
Temporarily Abandoned | TA
Can't Access. Well is surrounded by crops.

prior photo: 2022



Photo #2

State Lease 81 23-16 Battery site
Inactive | Shut-down
Equipment documented: Fac. ID 481570



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STATE LEASE 81-66N64W/16NESW

Location #: 326993



Photo #3

State Lease 81 23-16 Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources