

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-FEDERAL-66S102W/34SENE

Location ID: 322464

Date: 9/8/2025



Location Overview/Weeds – Photo #00623



Location – Photo #00624

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-FEDERAL-66S102W/34SENE

Location ID: 322464

Date: 9/8/2025



Location/Weeds – Photo #00634



Location/Weeds – Photo #00626

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-FEDERAL-66S102W/34SENE

Location ID: 322464

Date: 9/8/2025



Location/Weeds – Photo #00633



Labels Missing Required Information – Photo #00628

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-FEDERAL-66S102W/34SENE

Location ID: 322464

Date: 9/8/2025



Labels Missing Required Information – Photo #00629



Labels Missing Required Information – Photo #00630

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-FEDERAL-66S102W/34SENE

Location ID: 322464

Date: 9/8/2025



Trash/Debris In Secondary Containment – Photo #00627



Trash/Debris – Photo #00636

Audit Photos

Location Name: VISION ENERGY LLC, CALF CANYON-FEDERAL-66S102W/34SENE

Location ID: 322464

Date: 9/8/2025



Wildlife Entry Hazard – Photo #00632