

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: GRENEMYER-61N67W 26NESE

Loc ID: 331818

Inspection: 718600911

Form 44 Doc # 404349292

Exhibit A

CA: Staff did not observe a Form 44 per Rule 1105.f.(2). A Form 44 was submitted (Doc 401959029) that includes this location ID (331818) but the flowline abandonment box and date are blank. Flowline facility ID 462375 remains Active. Submit a Form 44 off location flowline abandonment according to Rule 1105.f.(2).

CA Resolution: Operator has submitted Form 44 Doc #404349292 in order to comply with Rule 1105.f.(2).