

# Inspection Photos

Loc: 386512

Operator: MERIDIAN OIL INC

Inspection Date: 8/31/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the recontoured and reclaimed location. The perennial vegetation has fully established to reference area levels.



## Inspection Photos



**Photo 2.** Facing west at the location. Perennial vegetation has established throughout the location and consists of native grasses forbs, and shrubs.



## Inspection Photos



**Photo 3.** Facing southwest at the location which matches pre-existing conditions and contours of the terrain.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID:386512 | Date: 8/31/2025

## Inspection Photos



**Photo 4.** Facing south at the location.



## Inspection Photos



**Photo 5.** Facing east at the recontoured and reclaimed location. The location has achieved compliance of the 1004 Rules.

