

Inspection Photos

API: 017-06410

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 9/5/2025

County: Cheyenne



Inspection Photos



Photo 1. Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and vehicles shall not drive outside of the access road boundary. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06410 | Date: 9/5/2025

Inspection Photos



Photo 2. Facing south along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road.



Inspection Photos



Photo 3. Facing southwest toward the wellsite.



Inspection Photos




Photo 4. Sign is posted at the wellhead.

