

Inspection Photos
Location: McClave Gas Compressor Station
Location ID: 255965
Spill ID 2608158, Rem Project # 5701



Photo 1 –Facility Placard

Photo 2 – Entrance to Facility

Inspection Photos
Location: McClave Gas Compressor Station
Location ID: 255965
Spill ID 2608158, Rem Project # 5701



Photo 3 – Tank Battery

Photo 4 – Tank Battery

Inspection Photos
Location: McClave Gas Compressor Station
Location ID: 255965
Spill ID 2608158, Rem Project # 5701



Photo 5 – Tank Battery

Photo 6 – Leak on 90* elbow, impacted soils

Inspection Photos
Location: McClave Gas Compressor Station
Location ID: 255965
Spill ID 2608158, Rem Project # 5701



Photo 7 – Areas of impacted soils

Photo 8 – Areas of impacted soils

Inspection Photos
Location: McClave Gas Compressor Station
Location ID: 255965
Spill ID 2608158, Rem Project # 5701




Photo 9 – Leak at heater treater



Photo 10 – Areas of impacted soils