

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2025

Submitted Date:

09/12/2025

Document Number:

710500597

FIELD INSPECTION FORM

Loc ID 324881 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Hart, Dale	719-688-1638	dale@westernoperating.com	
Costa, Ryan		ryan.costa@state.co.us	
James, Steven	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213381	WELL	PA	04/21/2022	OW	061-06743	DAWSON 10	EI

General Comment:

This is an Environmental Inspection for the Dawson 10 well location located in Kiowa County, Colorado.
[API 061-06743](#)
[Location ID 324881](#)
[Rem 20894](#)

Inspected Facilities

Facility ID: 213381 Type: WELL API Number: 061-06743 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: This is an Environmental Inspection for the Dawson 10 well location, Remediation Project # 20894. At the time of inspection areas of distressed vegetation were observed within the boundaries of the well pad. The access road remains as a two-track road through the pasture.

Remediation Project # 20894 is active with the last Form submission, Form 27-S Doc # 403300980 received on 02/01/2023. The approved reporting schedule is listed as quarterly. The 2023 second quarter report is 861 days late.

Operator shall provide an updated Implementation Schedule for remediation project # 20894 in accordance with 913.d.

Corrective Action: In accordance with Rule 913.e.(3), Operator will adopt a quarterly reporting schedule (every 90 days). Operator shall submit a Supplemental Form 27-S within 15 days from receipt of this Field Inspection Report.

Date: 09/29/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500599	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7230838