

Inspection Photos

09/9/2025

Operator: QB ENERGY OPERATING LLC

#10844

Location ID: 334405

Inspection Doc: 718100799

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 3: Photos taken from the interim areas on the west end of the Location, facing south and north respectively. Photos examples showing interim areas of the Location are not progressing towards 1003.e standards; vegetation is predominantly Undesirable Plant Species such as Cheatgrass, Annual Wheatgrass and Russian thistle. Desirable perennial vegetative establishment (predominantly Crested Wheatgrass) is sparse.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 4: Continued from photo 3. Photo example showing vegetation within the interim areas are predominantly Undesirable Plant Species such as Cheatgrass, Annual Wheatgrass and Russian thistle. Desirable perennial vegetative establishment (predominantly Crested Wheatgrass) is sparse.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 5: Photos taken from interim areas/slopes on the south end of the Location, facing east. Slopes on the Location are largely bare, and vegetation is predominantly Undesirable Plant Species such as Cheatgrass, Annual Wheatgrass and Russian thistle.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 6: Photos taken from interim areas/slopes on the southeast end of the Location, facing north. Slopes on the Location are largely bare, and vegetation is predominantly Undesirable Plant Species such as Cheatgrass, Annual Wheatgrass and Russian thistle. Photo right also show sediment deposition due to sediment transport.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 7: Photo taken from the interim areas on the southwest end of the Location. Photo shows Salt Cedar (*Tamarix. sp.*) establishment within interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 8: Photo taken from the southwest end of the working pad surface, facing east. Photo shows port-john on Location; sanitary facility has not been physically secured pursuant to Rule 602.m requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 9: See comments under photo 8.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 10: Photo taken from the east end of the battery facility, facing north. Photo shows line at the facility appears to be leaking. Maintenance required; spill requires cleaning.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334405



Photo 11: Continued from photo 10. Photos show line at the facility appears to be leaking. Maintenance required; spill requires cleaning.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources