

Inspection Photos

09/9/2025

Operator: QB ENERGY OPERATING LLC

#10844

Location ID: 334084

Inspection Doc: 718100806

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334084



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334084



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334084



Photo 3: Signage at wells require updating to comply with Ruled 605.g.(3) and 605.d



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: QB ENERGY OPERATING LLC #10844
Location ID: 334084



Photo 4: Signage at the tank battery, and tank posted with incorrect Operator information.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334084



Photo 5: Photo taken from pipe equipment on the northeast end of the Location. Photo shows spill within containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334084



Photo 6: Photos taken from the interim areas on the north and south end of the Location. Desirable perennial vegetative establishment appears to be progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources