

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6503 From entrance to location



Photo # 6504 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6505 Location



Photo # 6506 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6507 Location



Photo # 6508 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6509 Location



Photo # 6510 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6511 Open ended load line



Photo # 6512 Open ended load line

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6513 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 6514 Rupture disc vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6515 Chemical tank lacks required labeling



Photo # 6516 Chemical tank lacks required labeling

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



**Photo # 6517 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**



**Photo # 6518 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6519 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife



Photo # 6520 Wellhead sign has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6521 Wellhead sign has previous operators name



Photo # 6522 Wellhead sign has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6523 Wellhead sign has previous operators name

Photo # 6524 Battery sign has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



Photo # 6525 Tank labels have previous operators name

Photo # 6526 Tank labels have previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-MARATHON 23A-11D (11 X Pad)

Location #: 335703



**Photo # 6527 Opening on cellar cover/wildlife hazard
/available for entry by wildlife**