

Inspection Photos
Location Name: J Brophy 1-3
API Number: 125-07214



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: J Brophy 1-3
API Number: 125-07214



3. Gas Meter inside Meter Shed.



4. Meter shed roof damage.

Inspection Photos
Location Name: J Brophy 1-3
API Number: 125-07214



5. View of abandoned flowline equipment.



6. Closed valve on inlet.

Inspection Photos
Location Name: J Brophy 1-3
API Number: 125-07214



7. No gas meter on the inside of the abandoned flowline meter shed.



8. Well location overview.