

Inspection Photos
Location Name: Murrain, M 3-30
API Number: 125-06838



1. Lease sign at location.

2. New Content/Quantity/Hazard sign at produced water tanks.

Inspection Photos
Location Name: Murrain, M 3-30
API Number: 125-06838



3. View of produced water tanks with sign.



4. Repaired meter shed door handle.