

Final Reclamation Inspection

August 25, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 462068

Inspection Document #: 718800784

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-HAYES-63N66W-TANK

1NWSW

Location ID: 462068



Photo 1. Photo taken of the tank battery location, facing northeast. Photo illustrates that final reclamation activities have not taken place and midstream equipment remains on the location.



Photo 2. Photo taken of the tank battery location, facing southeast. Photo illustrates a pile of material on the location.



Inspection Photos

Location Name: HSR-HAYES-63N66W-TANK

1NWSW

Location ID: 462068



Photo 3. Photo taken of the tank battery location, facing southwest. See comments under Photo 2.



Photo 4. Photo taken of the tank battery location, facing northwest. See comments under Photo 1.



Inspection Photos

Location Name: HSR-HAYES-63N66W-TANK

1NWSW

Location ID: 462068



Photo 5. Photo taken of the tank battery location, facing west. Photo illustrates that two meter houses remain at the location.



Photo 6. Photo taken of the tank battery location, facing southeast. See comments under Photo 5.



Inspection Photos

Location Name: HSR-HAYES-63N66W-TANK

1NWSW

Location ID: 462068



Photo 7. Photo taken of the reference area, north of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.

