

Audit Photos

Location Name: UTAH GAS CORP, TOPAZ-68S104W/14NWNW

Location ID: 324387

Date: 9/10/2025



Location Overview – Photo #00660



Location – Photo #00661

Audit Photos

Location Name: UTAH GAS CORP, TOPAZ-68S104W/14NWNW

Location ID: 324387

Date: 9/10/2025



Location – Photo #00667




Location – Photo #00663

Audit Photos

Location Name: UTAH GAS CORP, TOPAZ-68S104W/14NWNW

Location ID: 324387

Date: 9/10/2025



Gas Meter Calibration Overdue – Photo #00668

Stored Supplies – Photo #00666