

Final Reclamation and Stormwater Inspection

September 12, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 319234

Well Name: RAYMOND V. SARCHET UNIT B #2

Inspection Document #: 718600954

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: RAYMOND V. SARCHET UNIT B
#2
Location ID: 319234



Photo 1. Looking east down the access road.



Photo 2. Photo taken on the portion of access road outside irrigation circle. Gravel is present on the portion of access road outside the irrigation circle.

Inspection Photos
Location Name: RAYMOND V. SARCHET UNIT B
#2
Location ID: 319234



Photo 3. Looking west down the access road towards the tank battery. At the time of inspection crop was smooth brome turf/hay. The access road appears to be planted but is still visible.



Photo 4. Looking south across the tank battery location. A pipe riser remains on location (red circle).



Inspection Photos
Location Name: RAYMOND V. SARCHET UNIT B
#2
Location ID: 319234



Photo 5. Looking southeast down the access road from the tank battery towards the wellhead.



Photo 6. Looking east from the wellhead area. All oil and gas equipment has been removed from this area. The area has not yet been returned to cropland or recontoured.

Inspection Photos
Location Name: RAYMOND V. SARCHET UNIT B
#2
Location ID: 319234



Photo 7. Looking south from the wellbore area. See photo 6 comments.



Photo 8. Looking west from the wellbore area. See photo 6 comments.

Inspection Photos
Location Name: RAYMOND V. SARCHET UNIT B
#2
Location ID: 319234



Photo 9. Looking north from the wellbore area. See photo 6 comments.