

Final Reclamation and Stormwater Inspection

September 12, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 317595

Well Name: ECHEVERRIA #1

Inspection Document #: 718600964

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ECHEVERRIA #1
Location ID: 317595



Photo 1. Looking north down the access road. Undesirable weeds such as kochia and russian thistle are present at the entrance of the access road.



Photo 2. Photo taken around the midpoint of the access road. Some areas of the access road have less desirable vegetation coverage than surrounding reference area. List B noxious weed scotch thistle was present but dead at the time of inspection and may have been treated.

Inspection Photos
Location Name: ECHEVERRIA #1
Location ID: 317595



Photo 3. Photo taken near the entrance of the location. Areas of bare soil and lower vegetative coverage are present.



Photo 4. Looking north across the center of the location approximately where the separator was located. A patch of bare soil and undesirable weeds approximately 250 ft long is present. List B noxious weed scotch thistle is present on location, dead at the time of inspection.



Inspection Photos
Location Name: ECHEVERRIA #1
Location ID: 317595



Photo 5. Looking east across the location from the tank battery area. Desirable plant species such as crested wheatgrass and intermediate wheatgrass are present on location but the density appears lower than the surrounding reference area.



Photo 6. Looking south from the wellbore location. Vegetation on location does not appear uniform with bare soil patches present throughout the location. Undesirable weeds such as kochia, russian thistle and list C noxious weeds mullein, and field bindweed are present on location. Desirable vegetation is also present on location.



Inspection Photos
Location Name: ECHEVERRIA #1
Location ID: 317595



Photo 7. Looking east from the wellbore location. See photo 6 comments.



Photo 8. Looking north from the wellbore location. See photo 6 comments.



Inspection Photos
Location Name: ECHEVERRIA #1
Location ID: 317595



Photo 9. Looking west from the wellbore location. See photo 6 comments.



Photo 10. Reference area to the south of the location.

