

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404205561

Receive Date:
05/15/2025

Report taken by:
KRIS NEIDEL

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>SCOUT ENERGY MANAGEMENT LLC</u>	Operator No: <u>10779</u>	Phone Numbers
Address: <u>13800 MONTFORT DRIVE SUITE 100</u>		Phone: <u>(970) 551-8320</u>
City: <u>DALLAS</u> State: <u>TX</u> Zip: <u>75240</u>		Mobile: <u>(970) 902-0518</u>
Contact Person: <u>Cody Christian</u>	Email: <u>cody.christian@scoutep.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 35050 Initial Form 27 Document #: 403674297

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>483695</u>	API #: _____	County Name: <u>RIO BLANCO</u>
Facility Name: <u>A.C. Mclaughlin 14 lateral line</u>	Latitude: <u>40.148405</u>	Longitude: <u>-108.921629</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NWNE</u>	Sec: <u>14</u>	Twp: <u>2N</u>	Range: <u>103W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications CL Most Sensitive Adjacent Land Use Non Crop Land

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

The surface water within 1/4 mile is actually a dry ephemeral drainage located approximately 350 feet to the south.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste
- Other E&P Waste
- Non-E&P Waste
- Produced Water
- Workover Fluids
- Oil
- Tank Bottoms
- Condensate
- Pigging Waste
- Drilling Fluids
- Rig Wash
- Drill Cuttings
- Spent Filters
- Pit Bottoms
- Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	Surface and Subsurface	Visual, Sampling and Field Screening

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A water injection leak occurred at 10 PM on 1/7/2023. The leak was on the water lateral that feeds the AC McLaughlin 17 and AC McLaughlin 91 right off of the AC McLaughlin 14 location. The leak was found and shut in at the isolation valve. All proper notifications were made.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Preliminary soil samples were collected from beneath the repaired flowline on 1/17/2023. Preliminary soil samples were also collected from along the spill path on 5/17/2023. A total of eleven (11) grab samples analyzed for Table 915-1 parameters were collected at a depth of 1 foot below ground surface. Three (3) background samples were also collected from a depth of 1 foot and analyzed for a shortened list of Table 915-1 parameters. Results indicate elevated levels of TPH, dibenzo(a,h)anthracene, hexavalent chromium, SAR and HSB above background levels within the impacted area.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 6
Number of soil samples exceeding 915-1 4
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 17240

NA / ND

-- Highest concentration of TPH (mg/kg) 933
-- Highest concentration of SAR 20.7
BTEX > 915-1 No
Vertical Extent > 915-1 (in feet) 1

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 915-1 _____

Highest concentration of Benzene (µg/l) _____
Highest concentration of Toluene (µg/l) _____
Highest concentration of Ethylbenzene (µg/l) _____
Highest concentration of Xylene (µg/l) _____
Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
_____ Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Three (3) background samples were collected from undisturbed areas adjacent to the spill. Results may be found in the attached analytical results. A historical background sample associated with nearby past releases was also used as part of this site investigation. Results for the referenced historical background sample may be found under "Related Forms" for this update.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

Confirmation samples will be collected following the removal of TPH contaminated soils at SS5. Samples for additional delineation will be collected in the areas of SS5, SS10 and the spill origin.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? Yes

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted soils will be excavated and removed to land farm for remediation.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

TPH impacted soils will be excavated in 2025 and confirmation samples collected. Scout requests approval of a reduced analyte list on all future samples at SS3, SS5, SS6 and SS9 consisting of TPH, SAR and EC only.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation) _____ Yes _____ Excavate and offsite disposal
_____ Chemical oxidation _____ If Yes: Estimated Volume (Cubic Yards) 1

_____ Air sparge / Soil vapor extraction

Yes _____ Natural Attenuation

_____ Other _____

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation and reseeding will occur when remediation is completed where applicable and will follow the 1000 series regulations.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. 01/07/2023

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 01/07/2023

Proposed site investigation commencement. _____

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

This form serves as an update to sampling activities for REM #35050 since the submittal of the Initial Form 27 (Doc #403674297).

Subsequent soil samples were collected on April 24, 2025. Six (6) sample locations were sampled and analyzed for full Table 915-1 parameters with exceedances above local background levels of TPH (SS5), SAR (SS3, SS6 and SS9) and EC (SS9).

Results for the referenced historical background sample may be found under "Related Forms" for this update.

A small scale cleanup of TPH at SS5 is scheduled for 2025 and a confirmation sample at this sample location will be collected and analyzed for Table 915-1 TPH. Confirmation samples will also be collected at SS3, SS6 and SS9. Scout requests a reduced analyte list at these locations consisting of SAR and EC only. Additionally, samples for the purpose of additional delineation will be collected in the areas of SS5, SS10 and the spill origin. These samples will be analyzed for full Table 915-1 parameters.

Scout requests an annual reporting schedule for this project moving forward.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Cody Christian

Title: HSE Coordinator I

Submit Date: 05/15/2025

Email: cody.christian@scoutep.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: KRIS NEIDEL

Date: 09/16/2025

Remediation Project Number: 35050

COA Type**Description**

	Additonal vertical delineation is required at SS5
	The 5/17/2025 sample date lab data is not provided here or found in the project file. Provide all referenced Lab data.
	Annual reporting and sampling approved.
	Request for "modified list of contaminants of concern" is approved per Rule 915.e.(2).C.
4 COAs	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

404205561	FORM 27-SUPPLEMENTAL-SUBMITTED
404205843	SOIL SAMPLE LOCATION MAP
404205844	ANALYTICAL DATA SUMMARY TABLE(S)
404205846	ANALYTICAL RESULTS

Total Attach: 4 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)