

Remediation Status Sheet

Inspection Date: 09/11/2025 & 09/15/2025

Location Information

Operator:	KPK	Location Name:	Stromquist 4A - 9/11/25
Spill ID:	491349	County:	Weld
Remediation Project No:	NA	City/Township:	Frederick

Reporting Status

Spill Date:	09/11/2025	Last Form 27 Submitted:	NA
Spill Open?	Yes	Last Form 27 Doc No:	NA
Spill Closure Due:	12/10/2025	Next Form 27 Due:	NA

Sensitive Receptors

High Priority Habitat:	Yes	Notes:	Bald Eagle Active Nest Site Half Mile & Bald Eagle Roost Site
Wetlands:	Adjacent	Notes:	Riverine wetland
Surface Water:	< 100'	Notes:	Idaho Creek, Freshwater Pond
Residence:	100' - 500'	Notes:	
Water Well:	> 500'	Notes:	Excluding monitoring well permitted for Remediation Project No. 25606

Remediation Status*

Soil samples collected and submitted:	No	Notes:	
Soil Impacts remaining in-situ:	Yes	Notes:	Visual/olfactory indications of organic impacts observed
<i>Organics:</i>	Unknown	Notes:	
<i>Soil Suitability:</i>	Unknown	Notes:	
<i>Metals:</i>	Unknown	Notes:	
Soil POC achieved:	No	Notes:	
Impacts to groundwater**:	Unknown	Notes:	
Monitoring Wells Installed:	No	Notes:	
Groundwater POC achieved:	NA	Notes:	

*Remediation Status based off most current information per Form 19/27 submittal

**Impacts to groundwater include sheen/free product observed on groundwater, impacted soil in contact with groundwater, or analytical

POC = Point of Compliance

--	--	--	--