

Remediation Status Sheet

Inspection Date: 09/11/2025 & 09/15/2025

Location Information

Operator:	KPK	Location Name:	Stromquist 4A
Spill ID:	482194	County:	Weld
Remediation Project No:	25606	City/Township:	Frederick

Reporting Status

Spill Date:	05/15/2022	Last Form 27 Submitted:	6/11/2024
Spill Open?	No	Last Form 27 Doc No:	403749120
Spill Closure Due:	NA	Next Form 27 Due:	9/9/2024

Sensitive Receptors

High Priority Habitat:	Yes	Notes:	Bald Eagle Active Nest Site Half Mile & Bald Eagle Roost Site
Wetlands:	Adjacent	Notes:	Riverine wetland
Surface Water:	< 100'	Notes:	Freshwater Pond
Residence:	100' - 500'	Notes:	
Water Well:	> 500'	Notes:	

Remediation Status*

Soil samples collected and submitted:	Yes	Notes:	
Soil Impacts remaining in-situ:	Yes	Notes:	
<i>Organics:</i>	Yes	Notes:	
<i>Soil Suitability:</i>	Yes	Notes:	
<i>Metals:</i>	Yes	Notes:	
Soil POC achieved:	No	Notes:	
Impacts to groundwater**:	Yes	Notes:	
Monitoring Wells Installed:	Yes	Notes:	No wells have been installed at source; excavation remains open.
Groundwater POC achieved:	No	Notes:	Extent of inorganic impacts to groundwater undefined. Extent of organic impacts to groundwater outside of excavation appear defined.

*Remediation Status based off most current information per Form 19/27 submittal

**Impacts to groundwater include sheen/free product observed on groundwater, impacted soil in contact with groundwater, or analytical

POC = Point of Compliance