

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1134 PAD

Location ID: 315928

Date: 09/10/2025



Photo # 3109 Entrance to location



Photo # 3119 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1134 PAD

Location ID: 315928

Date: 09/10/2025



Photo # 3110 Location



Photo # 3115 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1134 PAD

Location ID: 315928

Date: 09/10/2025



Photo # 3137 SE corner of location



Photo # 3138 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1134 PAD

Location ID: 315928

Date: 09/10/2025



Photo # 3139 NW corner of location



Photo # 3140 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1134 PAD

Location ID: 315928

Date: 09/10/2025



Photo # 3124 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 3126 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1134 PAD

Location ID: 315928

Date: 09/10/2025



Photo # 3132 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 3134 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1134 PAD

Location ID: 315928

Date: 09/10/2025



Photo # 3144 Unmarked deadman