

Inspection Photos
Location Name: JOHN WEIGANDT B#1
Location ID: 320276



Photo#1 Pumpjack/Weeds still not taking care of from previous inspections. Document#715801429 and 717000448