

# Inspection Photos

**09/10/2025**

**Operator:** PETROLEUM RESOURCE MANAGEMENT  
CORP - #10421

**Location ID:** 436485

**Inspection Document #:** 718600966

Moffat County, CO

Logan Maxwell

Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: WPU 36-1  
Location ID: 436485



**Photo 1.** Photos 1-5 taken at the southeastern portion of the Location, near the cut slope where the cuttings waste was stored. Photos illustrate that stormwater BMPs are no longer functioning per good engineering practices. Stormwater has commingled with cuttings material and has moved onto the pad.



**Photo 2.** See comment under Photo 1.

Inspection Photos  
Location Name: WPU 36-1  
Location ID: 436485



**Photo 3.** See comment under Photo 1.



**Photo 4.** See comment under Photo 1.

Inspection Photos  
Location Name: WPU 36-1  
Location ID: 436485



**Photo 5.** See comment under Photo 1.



Inspection Photos  
Location Name: WPU 36-1  
Location ID: 436485



**Photo 6.** Photos 6-7 illustrate examples of weeds found along the perimeter berms and fill slopes of the Location. Photo illustrates Puncturevine.



**Photo 7.** See comment under Photo 7. Photo illustrates Canada thistle, which was apparent to be dying back, either through herbicides or dormancy.



Inspection Photos  
Location Name: WPU 36-1  
Location ID: 436485



**Photo 8.** Photo taken on the western portion of the pad, facing north. Photo illustrates that the rock/debris pile has been removed.



**Photo 9.** Photo taken near the entrance of the Location, facing south. Photo illustrates overview of Location. Additional trash/equipment has been removed.

