

# Inspection Photos

API: 017-06632

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 9/5/2025

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast toward the access road. The access road is impassible due to stormwater accumulating along the road. Since the well has been PA'd the road will need to be decompacted, regraded, and reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06632 | Date: 9/5/2025

## Inspection Photos



**Photo 2.** Facing southeast toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06632 | Date: 9/5/2025

## Inspection Photos



**Photo 3.** Facing toward the cut/capped wellhead. Contaminated material has been excavated from the wellhead and placed at the southeast side of the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06632 | Date: 9/5/2025

## Inspection Photos



**Photo 4.** East side of the location facing southwest. There are blacked stained soils at the east side of the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06632 | Date: 9/5/2025

## Inspection Photos



**Photo 5.** Facing toward southeast side of the location. The excavated impacted material was placed on a piece of plastic with no containment and some of the material has fallen outside of the liner. The plastic was also torn and compromised.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06632 | Date: 9/5/2025

## Inspection Photos



**Photo 6** . Facing northeast. The excavated impacted material was placed on a piece of plastic with no containment and some of the material has fallen outside of the liner. The plastic was also torn and compromised.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:017-06632 | Date: 9/5/2025