

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1013 PAD

Location ID: 314711

Date: 09/10/2025



Photo # 3186 Entrance to location



Photo # 3197 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1013 PAD

Location ID: 314711

Date: 09/10/2025



Photo # 3187 Location



Photo # 3194 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1013 PAD

Location ID: 314711

Date: 09/10/2025



Photo # 3202 SW corner of location



Photo # 3203 SE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1013 PAD

Location ID: 314711

Date: 09/10/2025



Photo # 3204 NE corner of location



Photo # 3205 NW corner of location