

Inspection Photos

09/08/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 311695

Inspection Doc: 719200189

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 311695



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 311695



Photo 2: Photos showing an overview of the location looking northeast and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 311695



Photo 3: A wattle that does not appear to be in use is present on the northern portion of the location near production equipment. Comply with Rule 606.d.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 311695



Photo 4: Staining is present on the working pad surface near the wellheads. Comply with Rule 912.a.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 311695



Photo 5: Photos showing the southern interim area. Cheatgrass and weedy annuals are dominant throughout some portions of the interim areas with Russian wildrye present in isolated patches.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 311695



Photo 6: Russian knapweed is present inside the fenced wellhead areas.
Comply with Rule 606.c.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 311695



Photo 7: Prickly Russian thistle and cheatgrass, both undesirable plant species, is present on the working pad surface and around the wellheads. Comply with Rule 606.c.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources