

Inspection Photos

09/08/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335546

Inspection Doc: 719200186

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335546



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335546



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335546



Photo 3: Photos showing portions of the northwestern and northern interim areas, respectively. Some portions of the interim areas are progressing towards 1003 reclamation requirements; other portions remain bare and appear to have compaction issues. Additional reclamation efforts may be necessary in these portions of the interim areas.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources



Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335546



Photo 4: Photos showing bare cut slopes on the eastern portion of the location behind production equipment. The Corrective Action to implement or maintain stormwater BMP's remains outstanding.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335546



Photo 5: Trailers, vehicles and other materials are being stored in the interim area. Removal is required. Comply with Rule 606.a.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335546



Photo 6: Graffiti appears to be present on tanks at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources