

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1136 From entrance to location




Photo # 1137 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1138 Location



Photo # 1139 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1140 Location



Photo # 1141 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1142 Location



Photo # 1143 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1144 Location



Photo # 1145 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1146 Location



Photo # 1147 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1148 Location



Photo # 1149 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1150 Location



Photo # 1151 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



**Photo # 1152 Rig sign at intersection on lease road not properly posted**



**Photo # 1153 Rig sign at intersection on lease road not properly posted**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1154 Rig sign at intersection on lease road not properly posted



Photo # 1155 Frac tanks lack required labeling

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1156 Frac tanks lack required labeling



Photo # 1157 Frac tanks lack required labeling

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617




Photo # 1158 Label on 110 bbl rolltop tank has previous operators name



Photo # 1159 Labels on 110 bbl rolltop tank have previous operators name

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1160 Rig tank lacks required labeling



Photo # 1161 Rig tank lacks required labeling

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC GRANLEE OM 09D I02 696

Location #: 335617



Photo # 1162 Rig tank lacks required labeling