

**KP Kauffman - ECMC Inspection Photos**

**Location: UPRR 43 Pan AM I #26**

**Date 09/17/2025**



**Signage at PA well; bottom of excavation**



**View of location; looking south**

**KP Kauffman - ECMC Inspection Photos**  
**Location: UPRR 43 Pan AM I #26**  
**Date 09/17/2025**



**Concrete trash/ debris**



**Unused equipment; electrical service**  
**Trash/ debris; well casing cut off and electrical/ pipe trash**