



LEASE INSPECTION FORM

Date 9/19/85

Operator CONOCO

Field MCLALLUM

Lease Name & No. MCLALLUM 41

County SACKSON

Tank Battery No. _____

Location 12-9N-79W
Legal Description

Type of Inspection well site

Water Inflow _____ (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)

Type of Tank

SKIM TANK PUMP JACK NON-OPERATIONAL

Pit No. 1 _____

Pit No. 2 _____

Pit No. 3 _____

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

MY LAND PLAT SAYS DRILL SITE

THIS well is completed

RECOMMENDED ACTION (If Required) CHECK FILE FOR FMS.

INSPECTOR SSK

Completed BUT NEVER PRODUCED, NOR IS CAPABLE OF PRODUCING.
COULD BE W.I. OR WATER SUPPLY IN FUTURE.