

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 09/17/2025



Photo # 3530 Entrance to location



Photo # 3537 Battery sign contains inaccurate nearest public road information



## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 09/17/2025



Photo # 3556 SE corner of location



Photo # 3557 SW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 09/17/2025



Photo # 3558 NE corner of location



Photo # 3559 NW corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 09/17/2025



**Photo # 3541 Erosion & transport of sediment on cutslope/sediment migrating onto location/insufficient BMP's**

**Photo # 3542 Erosion & transport of sediment on cutslope/sediment migrating onto location/insufficient BMP's**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 09/17/2025



**Photo # 3543 Erosion & transport of sediment on cutslope/sediment migrating onto location/insufficient BMP's**



**Photo # 3545 Erosion & transport of sediment on cutslope/sediment migrating onto location/insufficient BMP's**

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD

Location ID: 314651

Date: 09/17/2025



**Photo # 3549 Failure to minimize erosion & transport of sediment**



**Photo # 3551 Failure to minimize erosion & transport of sediment**