

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 268 From entrance to location




Photo # 269 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 270 Location



Photo # 271 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 272 Location

Photo # 273 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 274 Location



Photo # 275 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6897 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure/tank lacks integrity**

**Photo # 276 Tank failure/tank lacks integrity**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6898 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure/tank lacks integrity**

**Photo # 277 Tank failure/tank lacks integrity**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 6899 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure/tank lacks integrity

Photo # 278 Tank failure/tank lacks integrity

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6900 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure Multiple holes in tank/tank lacks integrity**

**Photo # 279 Tank failure Multiple holes in tank/tank lacks integrity**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Jun 6, 2025 at 10:50:58 AM



Sep 17, 2025 at 12:26:07 PM  
+39.551924, -108.115538  
18° N  
Garfield County

Photo # 6901 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure Multiple holes in tank/tank lacks integrity

Photo # 280 Tank failure Multiple holes in tank/tank lacks integrity

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 6902 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure Multiple holes in tank/tank lacks integrity



Photo # 281 Tank failure Multiple holes in tank/tank lacks integrity

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6903 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure Multiple holes in tank/tank lacks integrity**



**Photo # 282 Tank failure Multiple holes in tank/tank lacks integrity**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 6904 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure Multiple holes in tank/tank lacks integrity

Photo # 283 Tank failure Multiple holes in tank/tank lacks integrity

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6905 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure Multiple holes in tank/tank lacks integrity**

**Photo # 284 Tank failure Multiple holes in tank/tank lacks integrity**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6906 From inspection/audit 708906677 conducted on 06/06/2025 Tank failure Multiple holes in tank/tank lacks integrity**

**Photo # 285 Tank failure Multiple holes in tank/tank lacks integrity**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 6907 From inspection/audit 708906677 conducted on 06/06/2025 Liner in disrepair/liner needs maintenance

Photo # 286 Liner in disrepair/liner needs maintenance

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6908 From inspection/audit 708906677 conducted on 06/06/2025 Liner in disrepair/liner needs maintenance**

**Photo # 287 Liner in disrepair/liner needs maintenance**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6911 From inspection/audit 708906677 conducted on 06/06/2025 Hole in liner/liner needs maintenance**

**Photo # 288 Hole in liner/liner needs maintenance**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6912 From inspection/audit 708906677 conducted on 06/06/2025 Holes in liner/liner needs maintenance**

**Photo # 289 Holes in liner/liner needs maintenance**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6913 From inspection/audit 708906677 conducted on 06/06/2025 Hole in liner/liner needs maintenance**



**Photo # 290 Hole in liner/liner needs maintenance**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 6915 From inspection/audit 708906677 conducted on 06/06/2025 Hole in liner/liner needs maintenance

Photo # 291 Hole in liner/liner needs maintenance

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6916 From inspection/audit 708906677 conducted on 06/06/2025 Hole in liner/liner needs maintenance**

**Photo # 292 Hole in liner/liner needs maintenance**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



Photo # 6917 From inspection/audit 708906677 conducted on 06/06/2025 Hole in liner/liner needs maintenance

Photo # 293 Hole in liner/liner needs maintenance

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6918 From inspection/audit 708906677 conducted on 06/06/2025 Hole in liner/liner needs maintenance**

**Photo # 294 Hole in liner/liner needs maintenance**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 4 696 ECA Pad

Location #: 335778



**Photo # 6919 From inspection/audit 708906677 conducted on 06/06/2025 Liner in disrepair/liner needs maintenance**

**Photo # 295 Liner in disrepair/liner needs maintenance**