

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 698 From entrance to location




Photo # 699 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 700 Location



Photo # 701 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 702 Location



Photo # 703 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 704 Location

Photo # 705 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 706 Location



Photo # 707 Unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 708 Same unmarked deadman

Photo # 709 Same unmarked deadman

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 710 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife



Photo # 711 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 712 Wellhead sign lacks required information

Photo # 713 Wellhead sign lacks required information

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC UNOCAL 9-11D Pad

Location #: 335818



Photo # 714 Wellhead sign lacks required information

Photo # 715 Wellhead sign lacks required information