

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404192266
Receive Date:
05/29/2025

Report taken by:
John Heil

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>QB ENERGY OPERATING LLC</u>	Operator No: <u>10844</u>	Phone Numbers
Address: <u>1001 17TH STREET SUITE 1600</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Blair Rollins</u>	Email: <u>brollins@qb-energy.com</u>	Phone: <u>(970) 640-6919</u>
		Mobile: <u>(970) 640-6919</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 35902 Initial Form 27 Document #: 403770780

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>486120</u>	API #: _____	County Name: <u>RIO BLANCO</u>
Facility Name: <u>YCF 2-35-1 Waterline Release</u>	Latitude: <u>39.991028</u>	Longitude: <u>-108.356173</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NWSE</u>	Sec: <u>2</u>	Twp: <u>1S</u>	Range: <u>98W</u> Meridian: <u>6</u> Sensitive Area? <u>No</u>

SITE CONDITIONS

General soil type - USCS Classifications GC Most Sensitive Adjacent Land Use Non-Crop Land
Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Yellow Creek is located approximately 0.5 miles west.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste
- Other E&P Waste
- Non-E&P Waste
- Produced Water
- Workover Fluids
- Oil
- Tank Bottoms
- Condensate
- Pigging Waste
- Drilling Fluids
- Rig Wash
- Drill Cuttings
- Spent Filters
- Pit Bottoms
- Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	To be determined	Soil sampling and laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

While conducting pressure testing on the water gathering pipeline on the Location, a 2-inch thread was pulled from a check valve which then began releasing produced water onto the surface of the well pad. The pressure test was immediately stopped, and emergency response activities were initiated. Two absorbent booms were installed in each of the two stormwater drainages downgradient of the point of release (POR), and fluid recovery operations immediately began using water transport trucks. Additionally, an earthen berm was constructed surrounding the spill path to prevent migration of impacts from leaving the pad surface through ongoing snowmelt. Approximately 15 barrels (bbls) of produced water was released from the gathering line and was contained to the working surface of the Location. As of March 4, 2024, 160 bbls of fluids, consisting mostly of snowmelt, have been recovered from the Location. The release was reported via Energy & Carbon Management Commission (ECMC) Form 19 Document 403694211 to open Spill/Release Point ID 486120. Form 27 Document 403770780 was later submitted to open Remediation Project 35902

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Soil samples will be collected as needed to delineate the horizontal extent of soil impacts. Background samples will be collected to characterize native levels of inorganic constituents at the Location. QB will analyze soil samples for the approved reduced analyte list of total petroleum hydrocarbons (TPH), benzene, toluene, ethylbenzene, xylenes (BTEX), 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, naphthalene, sodium adsorption ratio (SAR), pH, arsenic, and boron. See the attached Proposed Sample Diagram and Report of Work Completed (ROWC) associated with Form 27 Document 403770780 for details.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater has not been encountered during site investigation activities. If groundwater is encountered, QB will notify the ECMC and attempt to collect a representative sample for analysis.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 0
Number of soil samples exceeding 915-1 _____
Was the areal and vertical extent of soil contamination delineated? No
Approximate areal extent (square feet) 5000

NA / ND

_____ Highest concentration of TPH (mg/kg) _____
_____ Highest concentration of SAR _____
BTEX > 915-1 Yes
Vertical Extent > 915-1 (in feet) 15

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? Yes
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 915-1 _____

_____ Highest concentration of Benzene (µg/l) _____
_____ Highest concentration of Toluene (µg/l) _____
_____ Highest concentration of Ethylbenzene (µg/l) _____
_____ Highest concentration of Xylene (µg/l) _____
_____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
0 Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

See Proposed Sampling section and the ROWC associated with Form 27 Document 403770780 for details.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

QB Proposes to advance eight soil borings to delineate the horizontal extent of impacts, one in each cardinal direction from the point of release (POR) and material of interest (MOI) sample points. Once delineation is complete, QB will evaluate and provide a remediation strategy for ECMC review and approval on a Supplemental Form 27. See the attached Proposed Sample Diagram for additional details.

REMEDIAL ACTION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

On February 21, 2024, initial sampling support was completed to characterize soil impacts at the POR and spill path. Released fluids were contained to the working surface of the pad. One soil sample was collected directly beneath the POR at 0.5 feet below ground surface (bgs). Additionally, seven characterization samples were collected, four from points within the spill path, and three samples to represent points of compliance outside of the spill path. Analytical results of the spill path samples indicate compliance with Table 915-1 Residential Soil Screening Levels (RSSLs) except for TPH, xylenes, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, SAR, and arsenic. Analytical results of the point of compliance samples indicate compliance with Table 915-1 RSSLs except for pH and arsenic.

On March 6, 2024, Form 19 Document 403707728 was submitted to request a reduced analyte list of TPH, BTEX, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, naphthalene, SAR, pH, and arsenic and to request that results be compared to RSSLs. The ECMC approved the form and associated requests on March 11, 2024.

Between March 6, 2024, and April 9, 2024, three additional release investigations were completed with a hydro vacuum truck to confirm the removal of surface impacts along the spill path and to continue remedial excavation around the POR. Thirteen soil samples were collected: eight from points within the spill path (SB01, SB02, and SB08 through SB15), three soil samples were collected directly below the POR at depths ranging from 0.5 to 15 feet bgs, and two below SB15 to characterize material that was observed to have historic hydrocarbon staining. Analytical results of the spill path samples indicate compliance with Table 915-1 RSSLs except for TPH, benzene, ethylbenzene, xylenes, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, naphthalene, SAR, boron, and arsenic. See the ROWC associated with Form 27 Document 403770780 for details.

Soil Remediation Summary

<input type="checkbox"/> In Situ	<input checked="" type="checkbox"/> Ex Situ
_____ Bioremediation (or enhanced bioremediation)	Yes _____ Excavate and offsite disposal
_____ Chemical oxidation	_____ If Yes: Estimated Volume (Cubic Yards) _____ 12
_____ Air sparge / Soil vapor extraction	_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____
_____ Natural Attenuation	_____ Excavate and onsite remediation
_____ Other _____	_____ Land Treatment
	_____ Bioremediation (or enhanced bioremediation)
	_____ Chemical oxidation
	_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater has not been encountered at any point during the project. In the event that groundwater is encountered, QB will notify the ECMC and attempt to collect a representative sample for analysis.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Q2 2025 Proposed Sampling Plan

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Per Rule 705.b, and in line with guidance laid out in the SBAP, QB Energy has general liability insurance in the amount of \$5M, and QB Energy has umbrella insurance, which sits over the general liability insurance in the amount of \$65M. The umbrella and general liability insurance covers property damage, bodily injury to third parties, and sudden or accidental pollution under a combined \$70M.

Operator anticipates the remaining cost for this project to be: \$ 20000

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Any disturbance will be returned to the active working surface of the well pad for continued operation. When the site is decommissioned at a later date, it will be reclaimed in accordance with 1000 Series regulations.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. 07/21/2024

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/21/2024

Proposed site investigation commencement. 02/21/2024

Proposed completion of site investigation. 10/01/2025

REMEDIAL ACTION DATES

Proposed start date of Remediation. 02/21/2024

Proposed date of completion of Remediation. 08/01/2027

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

This form is being submitted to provide a Q2 2025 status update. QB Proposes to advance eight soil borings to delineate the horizontal extent of impacts, one in each cardinal direction from the POR and MOI sample points. Soil samples will be collected as needed to delineate the horizontal extent of soil impacts. Background samples will be collected to characterize native levels of inorganic constituents at the Location. QB will analyze soil samples for the approved reduced analyte list of TPH, BTEX, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, naphthalene, SAR, pH, arsenic, and boron. See the attached Proposed Sample Diagram and ROWC associated with Form 27 Document 403770780 for details.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Blair Rollins

Title: Environmental Specialist

Submit Date: 05/29/2025

Email: brollins@qb-energy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: John Heil

Date: 09/23/2025

Remediation Project Number: 35902

COA Type**Description**

	Comply with all outstanding COAs.
1 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

404192266	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
404192289	SITE INVESTIGATION PLAN
404363675	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)