

Inspection Photos

Location Name: PAPPENHEIM USX AB-67N64W/13SSW

Location #: 310329



Photo #1

Pappenheim USX AB 13-13 (123-26250) Wellsite

Shut-In | SI

CA: Invalid Emergency Number



Photo #2

Pappenheim USX AB 13-13 Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 310329



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: PAPPENHEIM USX AB-67N64W/13SWSW

Location #: 310329




Photo #3

Pappenheim USX AB 13-13 Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources