

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK #7318 PAD

Location ID: 315265

Date: 09/18/2025



Photo # 3603 Entrance to location




Photo # 3610 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK #7318 PAD

Location ID: 315265

Date: 09/18/2025



Photo # 3604 Location



Photo # 3608 Location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK #7318 PAD

Location ID: 315265

Date: 09/18/2025



Photo # 3614 NW corner of location



Photo # 3615 NE corner of location

## Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK #7318 PAD

Location ID: 315265

Date: 09/18/2025



Photo # 3616 SE corner of location



Photo # 3618 SW corner of location