

WELL NAME: COSWORTH FEDERAL 31-23, API #: 071-09201, INSP. # 716301548




PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.



PHOTO 3: UNUSED 2" POLY PIPE STORED ON LOCATION. REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 10-24-2025.



Network: Sep 24, 2025 at 10:40:04 AM MT
Local: Sep 24, 2025 at 10:40:04 AM MT
+37.248246,-104.7459
Las Animas Cour
Altitude:2308.3me
Speed:0.9km

PHOTO 4: AREA OF IMPACTED SOIL OUTSIDE OF SEPARATOR HOUSE APPEARS TO BE FROM DRAINING SEPARATOR ON THE GROUND. IMMEDIATELY DISCONTINUE DRAINING OILY WATER FROM SEPARATOR INTO LOCATION AND Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 10-24-2025.



PHOTO 5: THE STORMWATER POOLING ON LOCATION SHOULD BE DRAINED. INSTALL AND MAINTAIN BMP'S TO PREVENT STORMWATER POOLING ON LOCATIONS PER 1002 SERIES RULES. CA DATE 10-24-2025.