

Inspection Photos

Location Name: LETTERLY-USX AB-67N64W/23SSW

Location #: 310465



Photo #1

Letterly-USX AB 23-13 (123-26439) Wellsite

Temporarily Abandoned | TA

CA: Weeds



Photo #2

Letterly-USX AB 23-13 Battery site

Abandoned: ALL Equipment Removed

prior photo (2021)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: LETTERLY-USX AB-67N64W/23SWSW

Location #: 310465



Photo #3

Letterly-USX AB 23-13 Wellsite

Temporarily Abandoned | TA

Wellsite(s) entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources