

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150




Photo 1 Location.

Photo 2 Wellhead.

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 3 Wellsite sign.

Photo 4 Prime mover/Gas engine.

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 5 Separator.



Photo 6 ECDs.

Inspection Photos  
Location Name: Greenlaugh, Nauman 1-23  
Location ID: 320150



Photo 7 Tank Battery.



Photo 8 Tank battery sign.